

Colo

PATENT

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Application of:)		•
HIROAKI MIHARA ET AL.		:	Examiner: Juanita D. Stephens	
)	0 4 77 1 20	
Application No.: 10/071,799		:	Group Art Unit: 2853 U.S. Patent No.: 6,834,943 B2	
) :		
Filed: February 11, 2002)	- · · · · · · · · · · · · · · · · · · ·	
		:	Issued: December 28, 2004	
For:	A LIQUID DISCHARGE HEAD, A)		
	SUBSTRATE FOR USE OF SUCH	:		
	HEAD AND A METHOD OF)		Cante .
	MANUFACTURE THEREFOR	:	August 23, 2005	Certificate
				AUG 2 6 2005
Commissioner for Patents				of Correction
P.O. Bo	x 1450			0. 0 0 11
Alexand	ria, Virginia 22313-1450			

ATTENTION: CERTIFICATES OF CORRECTION BRANCH

REQUEST FOR CERTIFICATE OF CORRECTION UNDER RULE 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form (Form PTO-1050), in duplicate, is enclosed.

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

08/24/2005 JBALINAN 00000046 6834943

01-FC:1811

100.00 OP

Patentees' undersigned attorney may be reached in our Washington, D.C. office by telephone at (202) 530-1010. All correspondence should continue to be directed to our address given below.

Respectfully submitted,

Attorney for Patentees

Douglas W. Pinsky

Registration No. 46,994

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
Facsimile: (212) 218-2200

DWP/gmc

DC_MAIN 197467v1

CERTIFICATE OF CORRECTION

PATENT NO.

6,834,943 B2

DATED

December 28, 2004

INVENTOR(S) :

HIROAKI MIHARA ET AL.

Page 1 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 1

Line 43, "noises." should read --noise.--.

COLUMN 3

Line 37, "either one of" should read -- of any one of--.

Line 38, "being" should read --is--.

Line 51, "expression" should read --expressions--.

Line 57, "droplet" should read --a droplet--.

COLUMN 6

Line 17, "resign" should read --resist--.

COLUMN 8

Line 9, "electrode," should read --to serve as an electrode,--.

Line 19, "is formed" should read --formed--.

Line 52, "each" should be deleted.

COLUMN 9

Line 45, "electrode," should read --to serve as an electrode,--

COLUMN 10

Line 40, "electrode," should read --to serve as an electrode,--.

COLUMN 11

Line 28, "only" should read --only on--.

Line 47, "electrode," should read --to serve as an electrode,--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3801

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82)

DWP/gmc

PATENT NO. 6,834,943 B2

No. of add'l. copies @ 30¢ per page

⇒ _

CERTIFICATE OF CORRECTION

PATENT NO.

6,834,943 B2

DATED

December 28, 2004

INVENTOR(S) :

HIROAKI MIHARA ET AL.

Page 1 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 1

Line 43, "noises." should read --noise.--.

COLUMN 3

Line 37, "either one of" should read -- of any one of--.

Line 38, "being" should read --is--.

Line 51, "expression" should read --expressions--.

Line 57, "droplet" should read --a droplet--.

COLUMN 6

Line 17, "resign" should read --resist--.

COLUMN 8

Line 9, "electrode," should read --to serve as an electrode,--.

Line 19, "is formed" should read --formed--.

Line 52, "each" should be deleted.

COLUMN 9

Line 45, "electrode," should read --to serve as an electrode,--

COLUMN 10

Line 40, "electrode," should read --to serve as an electrode,--.

COLUMN 11

Line 28, "only" should read --only on--.

Line 47, "electrode," should read --to serve as an electrode,--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3801

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82)

PATENT NO. 6,834,943 B2

No. of add'l. copies @ 30¢ per page

 \Rightarrow ____

DWP/gmc

AUG 2 6 2005

CERTIFICATE OF CORRECTION

PATENT NO. :

6,834,943 B2

DATED

December 28, 2004

INVENTOR(S) :

HIROAKI MIHARA ET AL.

Page 2 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 12

Line 14, "only" should read --only on--. Line 42, "along" should read --with--.

COLUMN 13

Line 8, "214r" should read --214--.

Line 17, "electrode," should read --to serve as an electrode,--.

COLUMN 16

Line 45, "higher approximately two times" should read --approximately two times higher--. Line 48, "at a time," should read --at the same time,--.

COLUMN 18

Line 27, "didoes" should read --diodes--.

MAILING ADDRESS OF SENDER:

PATENT NO. 6,834,943 B2

FÎTZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile

No. of add'l. copies @ 30¢ per page

Form PTO 1050 (Rev. 3-82)

DC_MAIN 197467v1

DWP/gmc

<u>□</u>

CERTIFICATE OF CORRECTION

PATENT NO. :

6,834,943 B2

DATED

December 28, 2004

INVENTOR(S) :

HIROAKI MIHARA ET AL.

Page 2 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 12

Line 14, "only" should read --only on--. Line 42, "along" should read --with--.

COLUMN 13

Line 8, "214r" should read --214--.

Line 17, "electrode," should read --to serve as an electrode,--.

COLUMN 16

Line 45, "higher approximately two times" should read --approximately two times higher--. Line 48, "at a time," should read --at the same time,--.

COLUMN 18

Line 27, "didoes" should read --diodes--.

MAILING ADDRESS OF SENDER:

PATENT NO. 6,834,943 B2

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile

No. of add'l. copies @ 30¢ per page

Form PTO 1050 (Rev. 3-82)

DWP/gmc

DC_MAIN 197467v1

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

6,834,943 B2

DATED

December 28, 2004

INVENTOR(S) :

HIROAKI MIHARA ET AL.

Page 3 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 19

Line 6, "nicated" should read --nicating--, and "forms" should read --forming--. Line 42, "supplies." should read --liquid supply.--.

Line 54, "materialize" should read --realize--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3801

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82)

DC_MAIN 197467v1

DWP/gmc

No. of add'l. copies

@ 30¢ per page

PATENT NO. 6,834,943 B2

Staple Here Only! Staple Here ALINER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

6,834,943 B2

DATED

December 28, 2004

INVENTOR(S) :

HIROAKI MIHARA ET AL.

Page 3 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 19

Line 6, "nicated" should read --nicating--, and "forms" should read --forming--.

Line 42, "supplies." should read --liquid supply.--.

Line 54, "materialize" should read --realize--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3801

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82) DC_MAIN 197467v1

@ 30¢ per page

No. of add'l. copies

PATENT NO. 6,834,943 B2